



# SOLIDOME dūmu šalinimo pavaros montavimo instrukcija

## SOLIDOME heat and smoke extraction system install guide




Traversa/Traverse




Sraigtas/Screw DIN 7504K 6,3x60




Pavara/Opening device




Sraigtas/Screw DIN 7504K 6,3x19








Laido schema Wire scheme	Spalva Color	Atidaryti Open	Uždaryti Close
	Rudas Brown	+	-
	Mėlynas Blue	-	+



8x DIN7504 K 6,3x19





8x DIN7504 K 6,3x19

